Approved For Release 2001/08/02 : CIA-RDP78-02820A001100050038-3

UNITED STATES GOVERNMENT

# Memorandum

25Х1А то

The Files:

T. O. 7

EP 65-277

DATE: 7 September 1965

25X1A9а FROM :

SUBJECT:

Inspection Report No. 9 - OS-12 with

25X1A5a1 25X1A

Project Description:

The OS-12 is a compact, stable, variable frequency oscillator. It has a frequency range of 2 - 30 Mc without any multiplication, spurious output of -65 db, and an accuracy of ± 1000 cps. The output power (3.0 V peak to peak across 200 ohms) is 5.0 mw and the input power at 12 V (± 10 percent) is 360 mw. The approximate size of the OS-12 is 4" x 2" x 1".

2. Contractual Information:

a. Initial Cost:

b. Request for Procurement Action: 18 September 1964

25X1A1a

25X1A5a1

c. Initiation Date: 28 October 1964

d. Completion Date: 21 June 1965

e. Deliverable Items: One engineering model - 28 May 1965; Monthly

Reports - on/before first of each month; Equipment Instruction Manuals - on/before 21 June 1965; Final Engineering Report - on/ before 21 June 1965; one set reproducible drawings, specifications, and additional 5 copies of each - on/before 21 June 1965

3. Date of Meeting: 27 August 1965

25X1A 4. Place of Meeting:

5. Persons Attending:

Agency

Non-Agency

25X1A9a

The state of the s

6. Contractor's Performance.

## Approved For Release 2001/08/02 Approved For Release 2001/08/02

EP 65-277

Inspection Report No. 9 - OS-12 with SUBJECT:

25X1A5a1

25X1A

#### Contractor's Performance: 6.

- On schedule and expected to remain so: No
- Within obligated funds and expected to remain so: No b.
- Satisfactory technical progress: Yes

#### Project Status: 7.

25X1A5a1

is still plagued with a problem of oscillation when inserting the PC board containing 68 - 69 Mc IF and mixer into the case. Also, a problem in obtaining a sufficiently reliable loop lock-up at the lower 10 Mc of the 2 - 30 Mc tuning range. This problem is due to low amplitude signals from the spectrum generator in the first ten megacycles of tuning range to the 68 - 69 IF amplifier and mixer where believe that by relock-on is attained. placing a now unused AGC circuit already on this last troublesome PC board with a DC amplifier the problem will be eliminated. believes that he has solved the oscillation problem but this must

25X1A5a1

await the PC board's return to the case.

25X1A5a1

25X1A5a1

indicated that as of the 15th of August over expended the contract by \$9,636 and estimates 4 - 5 additional man weeks (at \$500/man week) of labor to finish the project. This includes time for replacing the faulty Amelco flat-packs. has not, however, contacted OL as to a possible overrun.

25X1A5a1

25X1A5a1

There are two other areas where the OS-12 is not meeting its original expectations. The first is power consumption. The design goal was for a 300 to 400 mw input power. However, that due to transients in the RT-49 power supply system (when keyed) a power-hungry voltage regulator would be needed. measured 25X1A5a1 the power consumption in my presence. The OS-12 was drawing 800 mw from the power supply. The second area of disappointment is that the

25X1A5a1

goal of a. . .

### Approved For Release 2001/08/02 : CIA-RDP78-02820A001100050038-3

EP 65-277

SUBJECT: Inspection Report No. 9 - OS-12 with

25X1A5a1

25X1A5a1

goal of a \$400 - \$500 production cost does not look very imminent.

believes that as the OS-12 now stands production would be around \$900 to \$1000 per unit in small quantities. A large contributor to this cost would be the temperature compensation of the 152 - 180

Mc voltage controlled oscillator. The compensation tolerances are

25X1A5a1

believes there is a way around this probably in the form of using three VCO's each tunable over a 10 Mc portion of the 150 - 180 Mc band. With the above and other considerations, I believe a lower production cost is certainly possible.

11

25X1A5a1

25X1A9a

Distribution:

R&D Subject File
Engineering Section, CB/PD/OL
R&D Lab
OC-OS
OC-E/ESB
Monthly (2)
EP Chrono

25X1A9abC-E/R&D-EP

chw (7 September 1965)